- curvature, rough pavement conditions, no curb/gutter, and no sidewalk. The proposed project will improve these conditions and bring the roadway to current standards.
- 8) How wide is the proposed sidewalk? 8 feet
- 9) What public involvement has been done to date? Two public meetings: one open house and one presentation. Additionally, Edgewood Road was mentioned in 19 city council meetings, including were 27 remarks and 5 actions.
- 10) Photos would have been helpful to determine the condition and if the utilities are in fact absolutely necessary.
 - Some photos and heatmaps will be provided during the meeting. Significant drainage work has been completed in the last 15 years in a piecemeal fashion to a less than optimal level of service. The water system is at its end of life. Nine water breaks have occurred in 1,616 feet of pipe. The ditch on the west side cannot be maintained due to the gas line which is about 2 inch deep in the ditch. Columbia Gas and professionals say this area has some of the worst utilities they have ever seen.

